




VR1395




VR1397




VR1399




VR1480



VR2002



- VR1480: VR337, VR369, VR1472, VR1474A, VR1475, VR1476B, VR1478A, 2xVR5255
 VR1395: 6xVR598, 2xVR1390+, 8xVR1392+, 8xVR1393+
 VR1397: 4xVR1392, 2xVR1393, 4xVR1394, 2xVR1479
 VR1399: 4xVR598, 2xVR1361, VR1479, 4xVR1394
 VR2002: VR22, 2xVR44, VR45, VR93, VR94A, VR123, VR1902



VOLA A/S
 Lunavej 2
 DK-8700 Horsens
 Tlf : + 45 7023 5500
 Fax: + 45 7023 5511
 sales@vola.com
 www.vola.com

VOLA FS3

Dato

Nov. 11

Rev.

3

Blad

SB53.2